

ИНСТРУКЦИЯ по СБОРКЕ AVT101(Cus2216)

PART	QTY	ITEM	
A	2	吊臂	
B	18	M6x45	
C	4	M6x60	
D	12	M6x16	

PART	QTY	ITEM	
E	16	M6x16	
F	16	M4x20	
G	12	M4x30	
H	50	完美贴	

PART	QTY	ITEM	
K	4	100*60*3	
L	1	M4	
M	1	M6	
N			

